Fig. 1




Fig. 2




Fig. 3





Fig. 4

Slipping torque Measurement temperature: RT



O: Present Invention Products (Examples)

△: Conventional press-fitting type (Comparative Examples)